


1	ORG		EXIT AT 18' EXTEND 3'			
2	BLK		EXIT AT 18' EXTEND 3'			LUBE TEMP ISSPRO R8959-03
4	+5V LUBE PSI	WHT/RED	EXIT AT 18' EXTEND 3'	A		
5	LUBE PSI	BRN	EXIT AT 18' EXTEND 3'	B		DT06-3S
6	GND	BLK/WHT	EXIT AT 18' EXTEND 3'	C		LUBE PSI 500PSI MSP-600-500-O-3-N-1 MEASUREMENT SPECIALTIES
14	+5V TRANS PSI	WHT/RED	EXIT AT 2' EXTEND 6'	A		DT06-3S
15	TRANS PSI	WHT/GRN	EXIT AT 2' EXTEND 6'	B		TRANS PSI 500PSI
16	GND	BLK/WHT	EXIT AT 2' EXTEND 6'	C		MSP-600-500-O-3-N-1 MEASUREMENT SPECIALTIES



HPD26-24-31SE-L015

DWG#: X275	DWG NAME: HARNESS, PUMP/LUBE/TRANS PUMPCO	DATE: 11/07/05
File: C:\DRAWINGS\X275HNS PUMP-LIGHT-LUBE.DC	Dwg. By:	
Dwg Not to Scale	Revisions 0	Whitlock Instrument 1300 N. Texas Odessa, Tx 79761 WEB SITE: noflo.com CONTACT: LARRY RITCHIE 432-337-3412 FAX: 432-335-5926 larry@noflo.com
W.I.Part#	Num. Date:	
Material:		
Tolerance:		